NO. OF COPIES RECEIVE						Form C-103	
		1				Supersedes	
DISTRIBUTION		ki ki	FW MEXICO OIL CONS	FRVATION COMMIS	SION	C-102 and C Effective 1-	
ANTA FE		N	L# MEXICO OIL CONS	EKTA HOR COMMIS	J. J. T.	21.000140 1-	
ILE	-+-	+				5a. Indicate Ty	oe of Lease
.s.g.s.		1				State 🗶	Fee.
AND OFFICE	<del></del>	-				5. State Oil & C	Gas Lease No.
PERATOR		J				В 2	229
	SLINDE	Y NOTICES	S AND REPORTS ON	WELLS			
(DO NOT USE TH	USE "APPLICA"	OPOSALS TO DRI	LL OR TO DEEPEN OR PLUG !	BACK TO A DIFFERENT RES	SERVOIR.		
						7. Unit Agreem	ent Name
WELL T	WELL	OTHER-					
Name of Operator		_				8. Farm or Lea	
Phillips	Petroleum	Companu				9. Well No.	s E State
Address of Operator			<b>0</b> 3 <b>9</b>	707/O		9. Well No.	
	Phillips	Burrarus	, Odessa, Texas	טסקיעק		10 Field and F	Pool, or Wildcat
Location of Well	v	000		oc	20	Undeed	
UNIT LETTER	<u>M</u>	990 FE	ET FROM THE South	LINE AND99	FEET FROM	111111	
		10	TOWNSHIP 17-8	32_T	2		
THE WOST	LINE, SECT	ION TO	TOWNSHIP	RANGE JJOE	NMPM.		
mmm	mnn	15	. Elevation (Show whether	DF, RT, GR, etc.)		12. County	
			later			Lea	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Chook	Appropriate	e Box To Indicate 1		Report or Otl	ner Data	_
N	OTICE OF I				SUBSEQUENT		F:
19	OHCE OF I	NILNIION					
							<del></del>
FRENEM REMEDIAL WOR	RK 🗍		PLUG AND ABANDON	REMEDIAL WORK		ALT	ERING CASING
	RK		PLUG AND ABANDON	REMEDIAL WORK	OFNS.		ERING CASING
EMPORARILY ABANDON	RK .		PLUG AND ABANDON		===		<u> </u>
EMPORARILY ABANDON	RK			COMMENCE DRILLING	===		<u> </u>
EMPORARILY ABANDON	RK			COMMENCE DRILLING	===		=
. Describe Proposed work) SEE RULE	or Completed C		change plans	COMMENCE DRILLING  CASING TEST AND CEM  OTHER  tails, and give pertinen	t dates, including	estimated date (	s and abandonment
other  Describe Proposed work) SEE RULE  Reached TD  11.6# N-80,  Hewee comen salt/sx. P. plug w/2000	or Completed Citios.  of 4538'  A Cond cited w/150  lug to 45  #. Job o	on April asing (45 sx Class 17' w/6 b amplete 1	CHANGE PLANS	casing test and cemother	t dates, including 15-70, set 10 BW, 500 1 by 125 sx 14 Ran temp	estimated date of lass mad Class "H"	s 4-1/2" O.D.  flush and 10  coment w/8#  retated, bump
other  Describe Proposed work) SEE RULE  Reached TD  11.6# N-80,  Hewee comen salt/sx. P. plug w/2000	or Completed Citios.  of 4538'  A Cond cited w/150  lug to 45  #. Job o	on April asing (45 sx Class 17' w/6 b amplete 1	arly state all pertinent de  14, 1970, 7-7/8  34') at 4534'.  "H" coment w/4  bls acctic acid 2 neen 4-15-70,	casing test and cemother	t dates, including 15-70, set 10 BW, 500 1 by 125 sx 14 Ran temp	estimated date of lass mad Class "H"	of starting any proposes  4-1/2" O.D.  Flush and 10  coment w/8#  retated, being
other  Describe Proposed work) SEE RULE  Reached TD  11.6# N-80,  Hewee comen salt/sx. P. plug w/2000	or Completed Citios.  of 4538'  A Cond cited w/150  lug to 45  #. Job o	on April asing (45 sx Class 17' w/6 b amplete 1	arly state all pertinent de  14, 1970, 7-7/8  34') at 4534'.  "H" coment w/4  bls acctic acid 2 neen 4-15-70,	casing test and cemother	t dates, including 15-70, set 10 BW, 500 1 by 125 sx 14 Ran temp	estimated date of lass mad Class "H"	of starting any propos  4-1/2" O.D.  Flush and 10  cement w/8#  retated, bump

SUPERVISOR DISTINCT

DATE APR 2 9 1970

CONDITIONS OF APPROVAL, IF ANY: