

(May 1963)

DEPARTMENT OF THE INTERIOR

(Other instructions on reverse side)

GEOLOGICAL SURVEY

5. LEASE DESIGNATION AND SERIAL NO.

LC 029405(b)

6. INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

MCA

8. FARM OR LEASE NAME

MCA Unit #1

9. WELL NO.

256

10. FIELD AND POOL, OR WILDCAT

Wing G-SA Recons

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 20, T-17S, R-32E

12. COUNTY OR PARISH

Lea

N. Mex

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Continental Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 460, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

2590' FSL and 1310' FEL of Sec 20

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4007' gl

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PLUG OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Perf w/ 1 1/2 spf at 3808', 3812', 3815', 3818', 3821', 3686', 3688', 3690', 3693', 3697', 3701', and 3704'. Set pkr at $\pm 3730'$. Acid Frac w/ 6000 gals 15% HCL-NE acid at 10-12 BPM. Frac down casing w/ 20,000 gals trtd prod water and 35,000# 20/40 sand at 14-16 BPM. Run producing equipment. Plug back on production.

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE Administrative Supervisor

9-20-71

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

USGS (5) File

MCA(3)

*See Instructions on Reverse Side

APPROVED

SEP 21 1971

AKINOR R. BROWN
DISTRICT ENGINEER

RECEIVED

SEP 21 1971

OIL CONSERVATION COMM.
HOBBS, N. M.