

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

CONOCO INC.

3. Address and Telephone No.

10 DESTA DRIVE, STE 100 W, MIDLAND, TX 79705 (915) 686-5494

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

125 FSL & 1295 FEL, Sect 20, T17S, R32E

5. Lease Designation and Serial No.

LC-029405B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No. *Blk 2*
MCA Unit No. 269

9. API Well No.

30-025-23706

10. Field and Pool, or Exploratory Area

Majama (G-SA)

11. County or Parish, State

Lea, nm

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other *Perf & stimulate*
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

10-22-90 Miku. Unsat pmp. TFF at 415. 2ally out w/tbg. Trip bit & scrape to $\pm$ 4050. W/H w/pkr & WS. Set pkr at 3799. Tst lines to 3000#. Pmp 20 BBLs acid 3.5 BBLs/min at vac. pmp 100# salt 3.5 BBL/min at vac. Pmp 20 BBLs acid 3.5 BBLs/min at vac. pmp 200# salt 3.5 BBL/min at vac. Pmp 20 BBLs acid 3.5 BBLs/min at 550#. Pmp 250# salt 3.5 BBL/min at 550#. Pmp 20 BBLs acid 3.5 BBLs/min at 990#. Pmp 35 BBL flush 3.5 BBLs/min at 1400#. ISIP 1150# 5 min-210# 15 min vac. Ru to swab. Rel & POK w/pkr. Perf 3750-3776 w/53 shots 2 JPF. DIH w/ RBP & pkr. Set pkr at 3810. Tst RBP to 2000#. Set pkr at 3676. Pmp $\pm$ 5 BBL wtr 3 BBL/min at $\pm$ 50. acid pmp 7.5 BBL acid. Press went to 2600#. Spot 7.5 BBL acid to pkr. Close by pass. Flush at 2500#. Press came back upon csq to 1050#. Set 3.5 BBL acid into form. Press came back on csq. SITP 1400#. Fluid down

14. I hereby certify that the foregoing is true and correct

Signed

Christine A. Neff

Title

ADMIN. ASSISTANT

Date

8-7-91

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date