

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
CONTINENTAL OIL COMPANY

3. ADDRESS OF OPERATOR
Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1345' FNL & 660' FEL of SEC. 33

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3961' DF

5. LEASE DESIGNATION AND SERIAL NO.
LC 029405 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
059001

7. UNIT AGREEMENT NAME
MCA Unit Repr.

8. FARM OR LEASE NAME
MCA UNIT

9. WELL NO.
275

10. FIELD AND POOL, OR WILDCAT
MALJ. G-SA REPRD.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 33, T17S, R32E

12. COUNTY OR PARISH
LEA

13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

REPR. SURF. WATERFLOW

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

IT IS PROPOSED TO REPAIR SURFACE WATERFLOW AS FOLLOWS:

SET RET. BP AT 3900'. RUN CBL-VOL 3850-1000'. SET PKR. $\pm$ 200' ABOVE CMT. TOP. PERF W/ 2-JSPF OVER 2-3' INTERVAL AT $\pm$ 15' ABOVE CMT. TOP. HOOK-UP TO 8 5/8 X 5 1/2" ANNULUS & PUMP 100-200 BBLs. WATER TO ESTABLISH CIRC. SET GR DETECT. TOOL $\pm$ 50' ABOVE PERFS & PUMP DOWN ANNULUS 400 SX CMT W/ RADIOACTIVE SAND IN 1ST 50 SX, & FOLLOW W/ 300 SX CLASS "C" CMT. DISPL. W/ 28 BBLs. WATER. WOC 48 HRS. SQUEEZE DOWN TOG W/ 250 SX CMT, CMT. IN CSG. $\pm$ 50' ABOVE PERFS. WOC. DRL. OUT CMT. SWAB TEST SQUEEZE.

18. I hereby certify that the foregoing is true and correct

SIGNED

Wm. A. Burt

TITLE

ADMIN. SUPERV.

DATE

8/6/76

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

AUG 10 1976

BERNARD MOROZ

ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

USGS (5), MCA (3), FILE

RECEIVED

DEC 17 1976

OL. CONSERVATION COM. L.
HARRIS, N. M.