Form 3 160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

1	FORM APPROVED
	Budget Bureau No. 1004-01
	Expires: March 2 1 1000

Expires: March 3 1,1993

5. Lease Designation and Seriai No.

6. If Indian, Allonee or Tribe Name

IC	057210	

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICA TE	7. If Unit or CA, Agreement Designation
1. Type of Well	
Ou Well Gas Well Other Injection	8920003410
2. Name of Operator	8. Well Name and No.
Conoco Inc	MCA Unit, Well # 280
3. Address and Telephone No.	9. API Well No.
10 DESTA DR. STE. 100W, MIDLAND, TX. 79705-4500 (915) 686-5424	30-025-23740
4 Location of Well (Footage, Sec., T. R. M. or Survey Description) (915) 686-5424	10. Field and Pool, or Exploratory Area
	Maljamar Grayburg/SA
2565' FNL & 1345' FEL, Sec. 28, T 17S, R 32E, Unit Ltr 'G'	11. County or Parish, State
(n) CHECK APPROPRIATE DOY(1) TO INDICATE	Lea
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	T. OR OTHER DATA

THE OF SUBMISSION	TYPE OF ACTION		
Subsequent Repon Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Casing Integrity Test	Change of Plans New Construction Non-Routine Fracrunng Water Shut-Off Conversion to Injection Dispose Water [Nole: Reponresults of multiplecompitiononW	

Completion or Recompletion Report and Log form.)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed to perform a casing integrity test on the well in preparation for requesting temporary abandonment approval. The following procedure will be followed:

- 1. POOH with production equipment.
- 2. Set a plug within 100' of the top perf.
- 3. Notify the BLM 24 hours before pressure tesing casing to 500 psi for 30 minutes.
- 4. RIH with tubing and circulate packer fluid.
- 5. POOH with tubing and fill hole with packer fluid.

When completed, a successful pressure test will be submitted with a reason and a request to temporarily abandon this well.

•	a request to temporarily	abandon this well.
	PETER WON	Syria 199
14. I hereby certify that the foregoing is true and correct Signed (This space for Federai or State office use)	Bill R. Keathly ROSWELL RESOURCE Title Sr. Regulatory Specialist	
Approved byConditions of approval if any:	Title	Date

BLM(6), NMOCD(1), SHEAR, PONCA, COST ASST, FILE ROOM

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its junsdiction.