

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N. M. 88240
SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985
CASE DESIGNATION AND SERIAL NO.

LC-029405 (b)

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
CONOCO INC.

3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1345' FSL & 2615' FEL

14. PERMIT NO.
API# 30-025-23745

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

MCA

8. FARM OR LEASE NAME

MCA Unit Btzy1

9. WELL NO.

285

10. FIELD AND POOL, OR WILDCAT

Maljamar G/SA

11. SEC., T., R., N., OR BLK. AND SURVEY OR AREA

Sec 19-17S-32E

12. COUNTY OR PARISH

Lea

13. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Bradenhead Sqz

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MIRU. Set RBP @ 3500'. Run CBL & TOC @ 2407. TDC by temp. Survey @ 2375'. Log showed poor cmt all the way w/ weakest point @ 620'. Shot 4 holes @ 620'. Set pkr @ 393'. Spot 2 sxs sd on RBP. Pump 1 bbl fresh wtr pad, attempt to pump 20 bbls flo-check. With 15 bbls gone, pressure went from 500* to 1200*. Rel pkr. Shot 4 holes @ 580'. Set pkr @ 393'. Pump 250 sxs class "H" cmt w/ 2% CaCl₂. Displace w/ 5 bbls wtr. DO cmt to 625'. Circ. clean. Tested sqz @ 500 psi for 20 mins. Sqz held. Rel RBP. Hang well on.

Approved by Eddie Seay ^{w/ MOCO} on July 24. Verbal app'l from B. Pitsche on 7/30/85

18. I hereby certify that the foregoing is true and correct

SIGNED

Eddie Seay

TITLE Administrative Supervisor

DATE

7/30/85

(This space for Federal or State office use)

Orig. Sd.

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

8-14-85

*See Instructions on Reverse Side