

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. UNIT AGREEMENT NAME <i>MCA Unit</i>	
2. NAME OF OPERATOR <i>Conoco Inc.</i>		8. FARM OR LEASE NAME <i>MCA Unit Bty. 2</i>	
3. ADDRESS OF OPERATOR <i>P.O. Box 460 - Hobbs, New Mexico 88240</i>		9. WELL NO. <i>No. 295</i>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <i>1345' FSL & 25' FFL - Unit Letter I</i>		10. FIELD AND POOL, OR WILDCAT <i>Barish-Mahama-Pensall / Mahama G-SA</i>	
14. PERMIT NO. <i>30-025-23824</i>		15. ELEVATIONS (Show whether DF, RT, CR, etc.) <i>3904'</i>	
		12. COUNTY OR PARISH <i>Lea</i>	
		13. STATE <i>NM</i>	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐

(Other) *Shut-Off Surface Waterflow* ☒
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

MIRU. Attempt to pump 15 BFW through Bradenhead valve at 450 psi maximum surface pressure. Repeat several times to insure water does not come to surface. Pump 2 BFW tagged w/ Iodine 131 radioactive tracer material down CSG-CSG annulus. Displace tagged fluid w/ fresh water. Rack out iron to Bradenhead valve. Lead-in w/ 2 bbls salt-saturated brine. Pump a 2 bbl cushion of fresh water. Pump 20 bbls Flow-Chek. Trail Flow-Chek w/ 150 sacks of class "H" cement w/ 3% CaCl₂. Displace cement through wellhead w/ fresh water. Shut-in Bradenhead valve & install pop-off valve set at 450 psi. Run producing equipment & place on production.

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* TITLE *Administrative Supervisor*

DATE *September 10, 1987*

FOR STATE OR FEDERAL OR STATE OFFICE USE:

APPROVAL OF COMMISSIONS OF APPROVAL, IF ANY:

TITLE

DATE *9-29-87*

*See instructions on Reverse Side

Under 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.
BLM-Carlstad (6) Hondo (2) Cities (1) Potosi-Land (1) T.O.