NO. OF COPILS RECEIVED		*	Form C-103		
DISTRIBUTION	NEW MÈXICO OIL CONSERVATION COMMISSION		Supersedes Old C-102 and C-10	Supersedes Old C-102 and C-103	
SANTA FE				Effective 1-1-65	
FILE					
U.S.G.S.			·	5a. Indicate Type of Lease	
LAND OFFICE			State	F••KX	
OPERATOR			5. State Oil & Gas	Lease No.	
COULTS	DY NOTICES AND REPORTS ON	WELLS		umminin	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)					
1. OIL GAS			7. Unit Agreement	Name	
WELL ST WELL OTHER- 2. Name of Operator				8. Farm or Lease Name	
Roger C. Hanks			C. M. Grah	C. M. Graham	
3. Address of Operator			9. Well No.		
P. O. Box 3148, Midland, TX 79702			2	2 10. Field and Pool, or Wildcat	
4. Location of Well				· /	
UNIT LETTER I 660 FEET FROM THE West LINE AND 1980 FEET FROM					
THE South LINE, SECTION 29 TOWNSHIP 16S RANGE 36E NMPM.					
				HHHH	
	15. Elevation (Show whether		12. County		
İIIIIIIIIIII	3927		Lea	<i></i>	
	Appropriate Box To Indicate N	-			
NOTICE OF I	NTENTION TO:	SUBSEQUE	NT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERI	NG CASING	
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG A	ND ABANDONMENT	
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB			
_		OTHER	······		
OTHER					
17 Describe Proposed or Completed O	perations (Clearly state all pertinent dete	l ails, and give pertinent dates, includin	ng estimated date of s	tarting any propose	
work) SEE RULE 1103.		-			
Operator plans to plu	ng and abandon according	to instructions from OC	C as follows:	:	
(actual footage will be supplied as work progresses)					
(10011111111111111111111111111111111111					
BP set @ <u>+</u> 12,900' wi	ith 35' cement on top.				
100' plug in and out of stub of 5÷1/2" csg.					
100' plug at top of Penn. if not behind pipe.					
100' plug at top of Wolfcamp if not behind pipe.					
100' plug at top of Abo if not behind pipe.					
100' plug at top of G	Glorieta if not behind pi	pe.			
100' plug 50' in and	out of casingshoe of 8-5	/8".			
100' plug in and out	of 8-5/8" stub.				
100' plug at top of salt if not behind pipe.					
100' plug in and out	of shoe of 13-3/8".				
10 sx of cement at su	enforce with marker				
Mud between all plugs					
Mud Detween all plays	•				
24 hour notice will h	be given to OCC before se	tting bottom plug.			
18. I hereby contily that the information	n above is true and complete to the best	of my knowledge and belief.			
ا لهمما (ا	the sold.	0 0 1		77	
SIGNED	THE TITLE	Owner-Operator	DATE <u>6-7</u>	-//	
		Mark the state of	HINE.	t 10 40=0=	
APPROVED BY	Kunyay TITLE		DATE	<u> </u>	
CONDITIONS OF APPROVAL, IF AN	* 64-pares 12	2/2/20			
	- Ay fared 12	11 2/7 /			

RECEIVED

377 (CMA)