

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.
LC 0572100-058698-A

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE

7. If Unit or CA, Agreement Designation

MCA Unit

1. Type of Well
 Oil Well Gas Well Other

8. Well Name and No.

322

2. Name of Operator

Conoco Inc.

9. API Well No.

300252423300

3. Address and Telephone No.

10 Desta Drive West, Midland, TX 79705

10. Field and Pool, or Exploratory Area

Maljamar Grayburg-SA

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1880' FNL & 560' FWL
Sec. 26, T-17S, R-32E

11. County or Parish, State

Lea, NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input checked="" type="checkbox"/> Other <u>add perforations</u>
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

It is proposed to clean out to PBTD, treat for scale, reperforate and acidize this well. Additional intervals in the Grayburg 6th and San Andres 7th zones will be opened.

PROCEDURE

- Clean out wellbore to PBTD (4220'),
- Reperforate Grayburg 6th and San Andres zones.
Current perfs: 3964', 3967', 3970', 4000', 4003', 4024', 4029', 4075', 4077', 4079', 4089', 4091'
New Perfs: 3964'-74', 3998'-4006', 4024'-34', 4036'-40', 4072'-4082', 4088'-4094'
- Treat for scale.
- Stimulate with 3780 gals 15% HCL-NE-FE.
- Return to production.

RECEIVED
NOV 8 11 35 AM '90

14. I hereby certify that the foregoing is true and correct

Signed Jerry Hoover Title Regulatory Coordinator Date 11-6-90

(This space for Federal or State office use)

Approved by _____ Title _____ Date 11-8-90
Conditions of approval, if any: _____