

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
IG 3974	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Re-entry of P&A'd well		7. Unit Agreement Name
2. Name of Operator Kaiser-Francis Oil Company		8. Farm or Lease Name Sombrero State
3. Address of Operator P.O. Box 21468 Tulsa, OK 74121-1468		9. Well No. 1
4. Location of Well UNIT LETTER <u>J</u> <u>3496</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>6</u> TOWNSHIP <u>16S</u> RANGE <u>34E</u> NMPM.		10. Field and Pool, or Wildcat North Hume (Wolfcamp)
15. Elevation (Show whether DF, RT, GR, etc.) 4161 GR		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Operations to Re-enter began 1/25/88.

1. Drilled to 1092'. Unable to go deeper. Drlg completed 2/1/88.

Plugging Operations began 2/2/88 - Finished 2/2/88.

1. Pumped 50 sx cmt plug from 750'-650'.
2. Pumped 100 sx cmt plug from 404'-300'.
3. Set 10 sx cmt plug @ surface.
4. Welded on cap w/ name & date well P&A'd

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>C. Jan Valkenburg</u>	TITLE <u>Production Administrator</u>	DATE <u>4-6-88</u>
OIL & GAS INSPECTOR		
APPROVED BY <u>[Signature]</u>	TITLE <u></u>	DATE <u>AUG 16 '88</u>
CONDITIONS OF APPROVAL, IF ANY:		

8