

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO 88

Form approved
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME MCA
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME MCA Unit 141/3
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 346
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit M 55' FSL & 1200' FWL	10. FIELD AND POOL, OR WILDCAT Mahamar G/SA
14. PERMIT NO. 30-025-24513	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 27-17S-32E
15. ELEVATIONS (Show whether DF, WT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other) repair surf. wtrflow

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MIRU
- ② Rig up pmp truck to bradenhead valve
- ③ Run tracer survey
- ④ Bradenhead sqz the csq-csq annulus as follows:
 - a. Lead-in w/ 2bbls salt saturated brine
 - b. Pmp 2bbl fresh wtr cushion
 - c. Pmp 20 bbls Flo-Chek
 - d. Tail-in w/ 230 sxs class "H" cmt
 - e. Displace cmt thru wellhead w/ fresh wtr
- ⑤ shut-in bradenhead valve & install pop-off valve set @ 800 psi
- ⑥ Return well to production

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Administrative Supervisor

DATE

11-20-85

(This space for Federal or State office use)

APPROVED BY

TITLE

ADMINISTRATIVE SUPERVISOR
CARLSBAD RESOURCE MGR

DATE

11-26-85

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

RECEIVED
NOV 27 1985
O.C.D.
HOBBS OFFICE