· •		Form
		Supersede « a
DISTRIBUTION	The second of th	C-102 and $(\cdot, \cdot)$ ?
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective - +
FILE		and the same of th
U.S.G.S.		5a. Indicate Type of # #
LAND OFFICE		State
		5. State Oil & Gas Lease
OPERATOR		
SUNDRY NOTIC	ES AND REPORTS ON WELLS SHILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVO MIT _** (FORM C-101) FOR SUCH PROPOSALS.)	
UO NOT USE THIS FORM FOR PROPOSALS TO USE "APPLICATION FOR PER	MIT - " (FORM C-101) FOR SUCH PROPOSALS.)	THE THE PARTY OF T
		7. Unit Agreemer Name
OIL GAS OTHER.	DRY HOLE	
2 Name of Operator		8. Farm or Lease Name
$\mathcal{D}$ $I$ $\mathcal{D}$ $=$ $a$		W. TT
3. Address of Operator		9. Well No.
D 426 PETROLEUM CE		<b>世</b> 1
D 426 TETROLEUM CE	NTER.	10. Field and Foo . or Wile is
Location of Well		
7 330	FEET FROM THE SOUTH LINE AND 330	- PERT FROM SHOE DATE
FAST WE SESSION 1/	TOWNSHIP TILS RANGE RASE	E NMPM.
CINE, SECTION		MILLIAN STATE OF THE STATE OF T
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		LEA XXXXX
Check Appropris	ate Box To Indicate Nature of Notice, Rep	ort or Other Data
NOTICE OF INTENTIO	N TO:   SUB	SEQUENT REPORT OF
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
<del>-</del>	COMMENCE DRILLING OPNS.	PLUG AND ABANDO - MENT
TEMPORARILY ABANDON	CHANGE PLANS CASING TEST AND CEMENT J	
PULL OR ALTER CASING		
	OTHER	
OTHER		
	Clearly state all pertinent details, and give pertinent date	es, including estimated date of starting av "
2 75/ -	TERMEDIATE AT 1440 FT.	AND PULL OUT TO UR AL
SHOOT OFF 8 18 IN	TERMEDIAL AT THE	
		1 Holf
SET 35 SACK PLU	G FROM 1442 UP INTO OPER	4 /NUPE;
SET 15 SACK PLUC	FROM 345 TO 745-INT	+ OUT OF 1378 DETAT 323
SET 63 SACK TEVE	FROM 345 TO 245 - IN-	
•	AND DRY HOLE MARKER AT	SURFACE
SET 10 SACK PLUG	AND DRY NOVE MARKEN	
	•	
8. I hereby certify that the information above is t	rue and complete to the best of my knowledge and belief.	•

Orig. Signed by Joe D. Ramey Dist. I. Sept.

		Ī
		•
	i.	