

- 10-16-77 RU Ryco wireline. GIH w/string shot. Unable to go below 5130'. Backed off fish at 5112' (1 jt below original top of tubing fish). String weight 28000# Unable to POOH due to high winds. Circ and cond mud.
- 10-17-77 No work.
- 10-18-77 Circ bottoms up. POOH. Left 3 DCs, jars, and bumper sub in hole (tbg anchor and fish apparently had moved down hole 220' when string parted). GIH w/full string of 2-7/8" DP to top of fish at 5099'. Screwed into fish. Worked string to 88000#-4½' stretch or tubing movement. RU Ryco wireline and GIH w/1" sinker bars to 5274'. GIH w/string shot to 5247' (top of jars). GIH w/6½' of ½" rod. Stopped 5486'. Worked string to 105,000#, no additional movement.
- 10-19-77 GIH w/string shot to 5094'-stopped. GIH w/1" sinker bar to top of jars at 5277'. GIH w/string shot 5466'. Fired string shot at 5353' with 5½ rounds of torque in pipe. Did not back off. GIH w/string shot at 5129'. Made mechanical back off at 5281'. Recovered drill collars, x-over and top section of jars. Left lower half of jars, bumper sub, and x-over in hole on top of tubing. S.D.O.N.

RECEIVED

1976-1977

OIL CONSERVATION COMM.  
HOBBS, N. M.