

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry Hole</u>		7. Unit Agreement Name
2. Name of Operator <u>C &amp; K PETROLEUM, INC.</u>		8. Farm or Lease Name <u>Shipp 27 "A"</u>
3. Address of Operator <u>P.O. Box 2546</u> <u>607 Midland Nat'l. Bank Bldg. Midland, Texas 79701</u>		9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>27</u> TOWNSHIP <u>16-S</u> RANGE <u>37-E</u> N.M.P.M.		10. Field and Pool, or Wildcat <u>Wildcat</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3778.1</u>		12. County <u>Lea</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug and abandon as follows:

Spot 30 sx. cement plug @ 11,665' - TD  
Spot 60 sx. cement plug @ 10,950' - top Penn  
Spot 40 sx. cement plug @ 10,100' - top Wolfcamp  
Spot 40 sx. cement plug @ 8,600' - top Abo  
Spot 40 sx. cement plug @ 6,300' - top Glorieta  
Cut off 8-5/8" casing @ 1222'  
Spot 40 sx. cement plug @ 1240'  
Spot 75 sx. cement plug @ 420'  
Spot 10 sx. cement plug @ surface  
Installed dry hole marker  
Job complete 10-2-75

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Administrative Supervisor</u>	DATE <u>10-17-75</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL &amp; GAS INSPECTOR</u>	DATE <u>JUL 9 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		