

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1983, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED
MAR 11 1992

D. C. D.
DISTRICT OFFICE

WELL API NO. 30-025-25324

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.
16274

7. Lease Name or Unit Agreement Name

NORTH EIDSON FEE

8. Well No.

1

9. Pool name or Wildcat
EIDSON MORROW, NORTH

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
CHISOS OPERATING, INC.

3. Address of Operator
P.O. BOX 10865 MIDLAND, TX 79702

4. Well Location
Unit Letter M : 660 Feet From The SOUTH Line and 660 Feet From The WEST Line

Section 34 Township 15S Range 34E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4075' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CIBP IN PLACE @ 12,900'. DUMP 35' CMT. ON TOP OF PLUG.
SET CIBP @ 12,668' and DUMP 35' CMT ON TOP OF PLUG.
SET CIBP @ 11,932' AND DUMP 35' CMT ON TOP OF PLUG.
SHOOT 5½" CSG. OFF @ 10,000' +/-.
SET 100' CMT. PLUG FROM 6200'- 6100' W/30 SX. (OPEN HOLE 7 7/8) TAGG.
SET 100' CMT. PLUG FROM 4580'-4480' W/ 30 SX. HALF IN & HALF OUT OF 8 5/8" csg. TAGG.
SET 100' CMT. PLUG FROM 1700'- 1600' W/ 30 SX.
SET PLUG ON THE SURFACE W/10 SX CMT. WELD CAP ON AND MARK WITH 4" PIPE.

THIS PLUG AND ABANDONMENT IS NOTED BY
DISTRICT I SUPERVISOR JERRY SEXTON
ON 3/5/92 FOR THE CLO

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

David D. Frederick

TITLE

O & G ANALYST

DATE

3/5/92

TYPE OR PRINT NAME

DAVID D. FREDERICK

TELEPHONE NO. (915)

686-9466

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

MAR 16

CONDITIONS OF APPROVAL, IF ANY: