Mud Program:

Surface to 450'	- gel and lime for hole conditions to 450'.
450 - 4550	- brine. Add lime and mud seal for seepage 10 pH.
4550 - 10000	- fresh water circulated through reserve pit.
10000 - 11300	 add brine to raise chlorides to 90 - 100,000 ppm 9.0 - 9.2# add starch to raise viscosity to 30 - 31 add KCL for weight.
11300 - 12600	- raise weight to 10.1#, viscosity 33, WL 10cc
12600 - 13200	- weight reduced to 9.2, viscosity 33.

