

SECTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW (ICO OIL CONSERVATION COMMISSION

Form 103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS		5a. Indicate Type of Lease	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		5. State Oil & Gas Lease No. LG-3421	
2. Name of Operator Gas Producing Enterprises, Inc.		7. Unit Agreement Name	
3. Address of Operator P.O. Box 235, Midland, Texas 79702		8. Farm or Lease Name Chambers 27 State	
4. Location of Well UNIT LETTER A 660' FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 27 TOWNSHIP 15-S RANGE 35-E NMPM.		9. Well No. 2	
15. Elevation (Show whether DF, RT, GR, etc.) 3980.3' KB		10. Field and Pool, or Wildcat Townsend Wolfcamp	
12. County Lea			

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Gas Producing Enterprises, Inc. proposes to plug and abandon the Chambers 27 State Well No. 2 as outlined below.

1. Spot 50 sack cement plugs at: 10,540-10,640', 9650-9750', 8020-8120', 6170-6270', 4650-4750' and 1840-1940'.
2. Spot 10 sack cement plug at surface.
3. Install dry hole marker and clean location.

NOTE: All intervals not cemented will be filled with 10.2# mud. No casing recovery.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE District Engineer DATE May 17, 1978

APPROVED BY Jerry Sexton TITLE Dist 1, Supv. DATE MAY 19 1978

CONDITIONS OF APPROVAL, IF ANY: