

1. Fee	
2. Date	
3. Amount	
4. Date	
5. Amount	
6. Date	
7. Amount	

50. Indicate type of Lease	
51. State of Lease	State
52. State of Lease	State
53. State of Lease	State
54. State of Lease	State
55. State of Lease	State
56. State of Lease	State
57. State of Lease	State
58. State of Lease	State
59. State of Lease	State

SUNDARY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR OPERATIONS IN WELLS OR IN CONNECTION WITH A WELL OR RESERVOIR. USE THIS FORM FOR REPORTS ON WELLS OR IN CONNECTION WITH A WELL OR RESERVOIR.)

1. GIL ☐ GAS ☐ OTHER ☒ DRY HOLE	7. Unit Agreement Name
2. Name of Operator	8. Name of Lease Name
3. Address of Operator	9. Well No.
4. Location of Well	10. Field and Pool, if any
UNIT LETTER <u>H</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660'</u> FEET FROM	<u>S. Shoo Ray Morris</u>
THE <u>East</u> LINE, SECTION <u>33</u> TOWNSHIP <u>16-S</u> RANGE <u>35-E</u> N.M.P.M.	
11. Elevation (Show whether BT, RT, GR, etc.)	12. County
<u>GR-3991'</u>	<u>Lin</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

PLUG AND ABANDON ☒

CHANGE PLANS ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPS. ☐

CASING TEST AND CEMENT JOB ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1102.

*See attached sheet of previous perforations & plugs. Plugging Procedure. ✓

1. TOH with 2-3/8" tubing.
2. Run a stuck pipe survey on the 5" 15# casing. If the casing is free below 10,000' cut the casing. If the free point is above 10,000' run a cement retainer and set @ 9900'. Squeeze the perforis from 10,113' to 10,118' with 100 sacks Class "H" cement. TOH with the tubing and cut the casing @ 9800'.
3. Spot 50 sacks Class "H" cement at the cut-off of the casing.
4. Spot 50 sacks Class "H" across the bottom of the 9-5/8" casing from 4900' to 4800'.
5. Spot a 35 sack plug at the surface.

It is hereby certified that the information above is true and complete to the best of my knowledge and belief.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature]

TITLE Completion Engineer

DATE 9/7/79

APPROVED BY [Signature]

TITLE COMMISSION DISTRICT

DATE SEP 14 1979

CONDITIONS OF APPROVAL, IF ANY: