DISTRIBUTION		Form C-103 Supersedes Old C-102 and C-103 Effective Laborators
FILE	NEW MEXICO DIE CONSERVATION COMMISSION	Effective 1-1-65
U.S.G.S.		Sa. Indicate Type of Lease
LAND OFFICE		State Fee
OPERATOR		5. State Oil & Gas Lease No.
(DO NOT USE T	SUNDRY NOTICES AND REPORTS ON WELLS THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
OIL X	GAS WELL OTHER-	7. Unit Agreement Name
2. Name of Operator	ating Company 14d	8. Farm or Lease Name
	ating Company, Ltd.	Gann
3. Address of Operator 400 Wilco		9. Well No.
4. Location of Well		10. Field and Pool, or Wildcat
4. Location of well	D 860 North 990	Caudill Permo Penn
UNIT LETTER	D . 860 FEET FROM THE NORTH LINE AND 990 FEET FROM	Canalli Lelino Lelin
Most	Q 15-S 36-F	
THE WEST	LINE, SECTION 9 TOWNSHIP 15-S RANGE 36-E NMPM.	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3947' KB 3931' GR	Lea ()
16.	Check Appropriate Box To Indicate Nature of Notice, Report or Oth	or Data
1		REPORT OF:
	332323211	NEI ON TOT.
PERFORM REMEDIAL W	ORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		
	CORRECTED Plug back &	recomplete X
OTHER		
17 Fiescribe Propose	d or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE	1 f03,	
4-15-86:	RUPU. Blew well down. Stripped off wellhead and install pkr. POH w/tbg. RIH w/Baker CIBP.	ed bor. onset noder h ba
4-16-86:	Set CIBP @ 13171'. Tst'd plug to 3000#. Held OK. Circ	hole. Spot 2 sxs Class
4 10 00.	"C" cmt on CIBP. TOC 13151'. RIH and perf 12,057' - 12,	
4-18-86:	Acidized well w/5800 gals 7½% HCL w/1000 SCF N ₂ /Bbl. Dro	pped 50 BS throughout
	Acidized well w/5800 gals $7\frac{1}{2}\%$ HCL w/1000 SCF N $_2$ /Bbl. Drojob. Shut well in 1 hour. Open on choke.	
4-30-86	Atoka tested tight.	, \
5-02-86:	Set RBP @ 10,509'. Perf Bough at 10,291' - 10,314' (19 holes).	
5-03-86:	· · · · · · · · · · · · · · · · · · ·	
5 10-86:	Acidize w/10,000 gals. 20% acid and 15 BS and test.	001 6
5-14-86:	Retrieve RBP at 10,509'. Set CIBP at 12,010'. Dump bail 20' of cement on CIBP.	
5-21-86:	Run bottom hole pump and rods. Set pumping unit. Put Bough Formation 10,291'-10,314' on	Boom numn
5-22-86:	Set pumping unit. Full bough Formation 10,231 10,314 on	beam pump.
	FOR RECORD	ONLY
		
18. I hereby certify th	at the information above is true and complete to the best of my knowledge and belief.	
12011	A forman and the second	r luna 10 1096
SIGNED (VILLE	N. Sourser TITLE Division Production Manage	r DATE June 10, 1986
∆aicini.	AL SIGNED BY JERRY CTUTO	
	AL SIGNED BY JERRY SEXTON ISTRICT I SUPERVISOR TITLE	DATE JUN 1 6 1986
APPROVED BY	TITLE TO THE PROPERTY OF THE P	