

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instructions
reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ <u>temp. shut-in</u>	7. UNIT AGREEMENT NAME <u>MCA</u>
2. NAME OF OPERATOR <u>CONOCO INC.</u>	8. FARM OR LEASE NAME <u>MCA Unit</u>
3. ADDRESS OF OPERATOR <u>P. O. Box 460, Hobbs, N.M. 88240</u>	9. WELL NO. <u>364</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>Unit H</u>	10. FIELDS AND POOL, OR WILDCAT <u>Maabamar G/SA</u>
14. PERMIT NO. <u>2494 2314 FNL & 554' FEL</u>	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec. 20-175-32E</u>
15. ELEVATIONS (Show whether DF, RT, OR, etc.) <u>30-025-27067</u>	12. COUNTY OR PARISH <u>Lea</u>
	13. STATE <u>NM</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) temporarily abandon

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- ① MIRV, Kill well if necessary
- ② Release permanent pkr @ 3557'
- ③ Fish Vann guns (top @ 4225')
- ④ Tag PBTD @ 4280'. Spot a balanced plug of 41sxs class "C" cmt from 3750'-3500'. Spot 1 ft³ of pea gravel on top of plug.
- ⑤ Tag top of pea gravel @ 3493'. Set 5 1/2" CIBP immediately above pea gravel. Circ. wellbore w/ 11 lb/gal CaCl₂ brine.

APPROVED FOR 12 MONTH PERIOD
ENDING 5/27/87

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

Administrative Supervisor

DATE

5-21-86

(This space for Orders of State office use)

APPROVED BY

[Signature]

TITLE

DATE

5-27-86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side