STATE OF GEW MEXICO	
OIL CONSERVATION DIVIS ON DISTRIBUTION DIVIS ON P. O. BOX 2088	Form C-103
SANTA FE, NEW MEXICO 87501	Revised 10-1-
U.S.G.S.	Sa. Indicate Type of Leuse
LAND OFFICE	State X Fun
OPERATOR	5. State Oil 6 Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO CHILL OR TO DELPLIN OR PLUG BALD TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" FORM C-1011 FOR BUCH PROPOSALS.)	11/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1
OIL CAS WELL OTHER. PXA	7, Unit Agreement Name
Amoco Production Company	State Ho Com
P. O. Box 68 Hobbs, NM 88240	9. Well No.
Location of Well UNIT LETTER K . 2310 FEET FROM THE SOUTH LINE AND 1942 FEET FROM	Wildcat Morrow
THE West LINE, SECTION 19 TOWNSHIP 16-S RANGE 35-E NMPM	
15. Elevation (Show whether DF, RT, GR, etc.) 4032.7' GL	12. County Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Ot NOTICE OF INTENTION TO: SUBSEQUENT	her Data TREPORT OF:
PLUG AND ABANDON REMEDIAL WORK APPRAARILY ABANDON COMMENCE DRILLING OPNS.	ALTERING CASING PLUG AND ABANOCHMENT
CHANGE PLANS CASING TEST AND CEMENT JQB OTHER	
OTHER	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including work) SEE RULE 1103.	estimated date of starting any propose
PxA by spot cementing with 100' plugs at the following intervals: 12425-12525 with 40 sacks of class H 11770-11870 with 40 sacks of class H 10680-10780 with 40 sacks of class H 9740- 9840 with 40 sacks of class H 6170- 6270 with 40 sacks of class H	
Spotted 100' plug 50' in (4930) and 50' out (5030) of intermediate ca	sing set at 4980.
Spotted 100' plug 100' inside intermediate casing from 1865'-1965'.	
Spotted 10 sacks of cement at surface	
Erected PxA marker. Location to be cleaned and leveled.	

1-GPM

1-Hou 1-W. Stafford, Hou

.f. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Mark Randolph Assist. Admin. Analyst

0+4 NMOCD, H

CONDITIONS OF APPROVAL, IF ANY:

1-Susp