

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
LG - 1472

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A	7. Unit Agreement Name
2. Name of Operator Amoco Production Company	8. Farm or Lease Name State HO Com
3. Address of Operator P.O. Box 68 Hobbs, NM 88240	9. Well No. 1
4. Location of Well UNIT LETTER K 2310 FEET FROM THE South LINE AND 1942 FEET FROM THE West LINE, SECTION 19 TOWNSHIP 16-S RANGE 35-E NMPM.	10. Field and Pool, or Wildcat Wildcat Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 4032.7' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

Propose to P & A

Spot 100' plug 12425-12525 with 40SX Class H cement.
Spot 100' plug 11770-11870 with 40SX Class 'H' cement.
Spot 100' plug 10680-10780 with 40SX Class 'H' cement.
Spot 100' plug 9740- 9840 with 40SX Class 'H' cement.
Spot 100' plug 6170- 6270 with 40SX Class 'H' cement.
Spot 100' plug 50' in and 50' out of intermediate casing set at 4980 with 40SX Class 'H' cement
Spot 100' plug 100' plug inside intermediate casing from 1865'-1965' with 40SX Class 'H' cemen
Spot 10 SX cement at surface. Erect a P&A marker.
(Verbal approval Jerry Sexton)

0 + 4 NMOC D,H 1-Hou 1-W.Stafford, Hou 1-GPM 1-Susp

18. I hereby certify that the information above is true, and complete to the best of my knowledge and belief.

SIGNED Jerry Mitchell TITLE Admin. Analyst DATE 9-4-81

APPROVED BY Jerry Sexton TITLE DATE
CONDITIONS OF APPROVAL, IF ANY: