

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, New Mexico 87505

WELL API NO. 30-025-27283	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. K-6874	
7. Lease Name or Unit Agreement Name NORTHEAST KEMNITZ	
8. Well No. 6	
9. Pool Name or Wildcat KEMNITZ CISCO	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4120' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

Name of Operator
ELK OIL COMPANY

3. Address of Operator
POST OFFICE BOX 310, ROSWELL, NEW MEXICO 88202-0310

4. Well Location
Unit Letter N : 660 Feet From The SOUTH Line and 1980 Feet From The WEST Line
Section 9 Township 16 SOUTH Range 34 EAST NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)
SEE RULE 1103

OCTOBER 20TH THROUGH OCTOBER 30TH, 2000: RIG UP PULLING UNIT, PULL OUT OF HOLE WITH TUBING, SET CIBP AT 12,350' WITH 35' CEMENT. PULL OUT OF HOLE. RUN IN HOLE WITH PERFORATORS, PERFORATE 36 HOLES FROM 11,890-11,094 AND 11,114-11,127. TRIP OUT WITH PERFORATORS. RUN IN HOLE WITH 2 3/8 TUBING AND PACKER. SET PACKER AT 11,020'. RIG UP HALLIBURTON, ACIDIZE WITH 3000 GALLONS CCA ACID. RIG UP SWAB, SWABBED BACK LOAD. RIG DOWN UNIT, PREPARE TO RIG UP PUMPJACK.

DECEMBER 5TH THROUGH DECEMBER 8TH, 2000: SET UP PUMPING UNIT. START PUMPING.

DECEMBER 8TH, 2000: PUMPED BACK BACKSIDE LOAD. TESTED DECEMBER 15TH, 2000.
8 BARRELS OIL, NO WATER, 20 MCF.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE PRESIDENT DATE 12/22/2000
TYPE OR PRINT NAME JOSEPH J. KELLY TELEPHONE NO. 505-623-3190

(This space for State Use)

APPROVED BY [Signature] TITLE Geologist DATE 12/22/2000
CONDITIONS OF APPROVAL, IF ANY:

IC