

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 300252746700
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-990
7. Lease Name or Unit Agreement Name West Knowles
8. Well No. 9
9. Pool name or Wildcat Drinkard <i>West Knowles</i>

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Conoco, Inc.	
3. Address of Operator 10 Desta Dr. Ste 100W, Midland, TX 79705-4500	
4. Well Location Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line Section 35 Township 16S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR 3768'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to temporarily abandon this well by the following measures:

1. RIH with tubing and 5- $\frac{1}{2}$ " RBP.
2. Set RBP 100' above the top Drinkard perforation @ 8204'.
3. Circulate packer fluid and pressure test Casing and RBP for 30 minutes.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Jerry W. Hoover* TITLE Sr. Conservation Coordinator DATE June 20, 1991  
TYPE OR PRINT NAME Jerry W. Hoover TELEPHONE NO. (915) 686-657

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: