

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease

State ☒Fee ☐

5. State Oil & Gas Lease No.

L-6800-4

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Kimbark Oil & Gas Company	8. Farm or Lease Name N. Mex 1-4 State Com
3. Address of Operator 1580 Lincoln St. Suite 700 Denver, Colo	9. Well No. #1
4. Location of Well UNIT LETTER <u>N</u> <u>3350</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM <u>West</u> LINE, SECTION <u>4</u> TOWNSHIP <u>16S</u> RANGE <u>35E</u> NMPM.	10. Field and Pool, or Wildcat Townsend Devonian
15. Elevation (Show whether DF, RT, GR, etc.) GL 4021; 4037 KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☒

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pulled Rods & Tubing. 9-12-84
2. Set Halliburton CIBP 12,785' w/5 sx (9-12-84). Cement on top of CIBP.
3. Run Free point @ 3772' (9-15-84).
4. Cut off 5-1/2" casing @ 3714' (9-17-84).
5. Set 50 sx cement plug Btm @ 4774' - Top 4284' (9-18-84).
6. Set 40 sx cement plug Btm @ 3844' - Top 3554' (9-18-84).
7. Set 40 sx cement plug Btm @ 1488' - Top 1333' (9-18-84).
8. Set 10 sx cement plug in Top of 8-5/8" csg (9-18-84).
9. Cut off 8-5/8" & 13-3/8" Below surface Flange - Welded Plate over 13-3/8" & 8-5/8" 3' below ground level. Installed dry hole marker - cleaned up & leveled location 9-19-84.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE District Superintendent

DATE 10-9-84

APPROVED BY

TITLE

OIL & GAS INSPECTOR

DATE

JAN 16 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT 11 1984

C. C.
HOBBS OFFICE