STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

we. or Corice Scccisco	Ī	
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR	T	

Orig. Signed by Les Clements

ON

we. or Corice Scccives	Ī	OIL CONSERVATION DIVIS	51		
DISTRIBUTION		P. O. BOX 2088			
SANTA FE		SANTA FE, NEW MEXICO 875	0 1		
FILE					
U.S.G.S.					

Form	C-	103	
Revis	e d	10-1	- 7

DISTRIBUTION	P. O. Bo	OX 2088	Revised 10-1-78
SANTA FE	SANTA FE, NE	W MEXICO 87501	***************************************
FILE		,	5a. Indicate Type of Lease
U.S.G.S.		•	State Fee XX
LAND OFFICE			5. State Oil 6 Gas Lease No.
OPERATOR]	·	5, State Off & Gus Lease No.
SLINDR	RY NOTICES AND REPORTS O	N WELLS	
(DO NOT USE THIS FORM FOR PRO	POSALS TO DRILL OR TO DEEPEN OF PLUG ION FOR PERMIT - " (FORM C-101) FOR S	BAC' TO'A DIFFERENT RESERVOIR. UCH PROPOSALS.)	
			7. Unit Agreement Name
OIL GAS			
well XXI well	OTHER-		8. Farm or Lease Name
			.4
Kennedy & Mitchel	1,lnc.		Tilley #758
3. Address of Operator	D CO 00007		l i
P.O. Box 27D	Denver, CO 80227		#1
4. Location of Well			10. Field and Pool, or Wildcat
C 3:	30 Nort	th LINE AND 2310 FEET FR	Shoebar
UNIT LETTER	PEET PROM THE	CINE AND	
Wast	35 1	6S 35F	
THE LINE, SECTION	OHTOWNSHIPT	.6S RANGE 35E NMF	** (///////////////////////////////////
	15. Elevation (Show whether	- DE BT CP atal	12. County
	3980'	GL	Lea ())))))
16. Check	Appropriate Box To Indicate	Nature of Notice, Report or C	Other Data
	NTENTION TO:		NT REPORT OF:
NOTICE OF IN	TENTION TO.	1	
	۲	-l	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	-)	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB XX	r
	_	OTHER	
OTHER]	
17. Describe Proposed or Completed Or	perations (Clearly state all pertinent d	etails, and give pertinent dates, includ	ng estimated date of starting any proposed
work) SEE RULE 1103.		•	
			•
Pan Q its 13-3/8	" AQ# H_AO casing Sc	et at 360'. Cmtd w/375 s	ks Class C omt
		pefore drilling plug. He	
		B'. Cmtd w/2600 sks Lite	
C cmt. Umt circ	. Pressure test csg and	I BOP stack to 2000#. He	Id okay.
		at 13,423'. Cmtd w/800	sks cmt. Press
test csg to 1500 _f	# before starting comple	etion. Held okay.	
		,	
		• • •	
•			
•			
10 11 11 11 11 11 11 11 11 11 11 11 11 1	n above is true and complete to the bes	it of my knowledge and belief.	
18. I nereby century that the information	^		•
\mathcal{A} 0 4 0	Q. V	Engineer	7/1/1/02
PICHED / Cabell U.	TITLE TITLE	Ling Tileet	
	-		