

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
V-135

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER	7. Unit Agreement Name
2. Name of Operator MWJ PRODUCING COMPANY	8. Farm or Lease Name Saunders 9 State
3. Address of Operator 1804 First National Bank Bldg Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>H</u> <u>1980</u> FEET FROM THE <u>North</u> <u>LINE AND</u> <u>660</u> FEET FROM THE <u>East</u> <u>LINE, SECTION</u> <u>9</u> <u>TOWNSHIP</u> <u>15S</u> <u>RANGE</u> <u>33E</u> <u>N.M.P.M.</u>	10. Field and Pool, or Vicinity <u>Upper Penn</u>
11. Elevation (Show whether DF, RT, GR, etc.) 4198.1' GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/30/84: MI & RU. Disassembled W/H & started pulling 1". LD 260 jts & SD ON.
1/31/84: Pulled & LD 41 jts 1". Pulled 2-3/8" tbg, fl pac pump cav, pkr & T/P. RU CRC & ran CIBP to 9700', dmpd 35' cmt on top. Pmpd 130 bbls 10# brine & SD ON.
2/1/84: RU Stickney & welded on left sub. Pulled 5 1/2" slips. Shot @ 9000', unable to get loose. Ran charge @ 8500', failed to go off. Ran charge to 8500', csg still stuck. Left 220000 pull on csg ON.
2/2/84: Shot off @ 8000', came free. Pulled & LD 45 jts. SD ON.
2/3/84: Pulled & LD 147 jts for tot of 192 jts. RD Stickney. RU Dowell & pmpd 120 bbls 10# salt gel & spt'd 40 sx cmt plug from 8050-7950'. SD ON.
2/4/84: Tagged plug 66' above cut-off. Sptd 35 sx cmt plug from 5700-5600'. Sptd 40 sx cmt plug from 4287-4187' w/3% CaCl. Waited 4 hrs. Tagged plug @ 4254' & loaded hole. Sptd add 35 sx cmt plug from 4254-4154'. Sptd 35 sx cmt plug from 1500-1400'. Sptd 10 sx cmt plug at surface. RD Dowell & SD ON & for Sunday.
2/6/84: RD & MO. Cut off W/H & installed dry hole marker. WELL P & A.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Pat Bishop TITLE Pat Bishop - Agent DATE 2/7/84

APPROVED BY David Cutavack TITLE OIL & GAS INSPECTOR DATE APR 2 1984

CONDITIONS OF APPROVAL, IF ANY