

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input checked="" type="checkbox"/> WELL GAS <input type="checkbox"/> WELL OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator READING & BATES PETROLEUM COMPANY		8. Farm or Lease Name Dickinson Cattle Co 33	
3. Address of Operator 810 North Dixie Blvd. Room 202 Odessa, Texas 79761		9. Well No. 3	
4. Location of Well UNIT LETTER "O" 660 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 33 TOWNSHIP 14-S RANGE 38-E NMPM.		10. Field and Pool, or WHdcat Pollock (Wolfcamp)	
15. Elevation (Show whether DF, RT, GR, etc.) 3760' GR		12. County LEA	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-17-82 Ran 11 jts. 13 3/8 casing 54.50# per ft. J-55 St&C. 17 1/2" hole cemented with 500 sx class "C" 2% Ca Cl. Circ. 100 sx cement to surface.
Nipple up B.O.P. Pressure Test @ 500#.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Don Kipgen</u>	TITLE <u>Production Superintendent</u>	DATE <u>9-28-82</u>
APPROVED BY <u>Eddie W. Dean</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>OCT 4 1982</u>

CONDITIONS OF APPROVAL, IF ANY: