Submit 5 Copies
Appropriate District Office
DISTRICT 1
P.O. Box 1980, Hobbs, NM 88240

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-104
Revised 1-1-89
Spe Instructions
At Bottom of Page

DISTRICT II P.O. Drawer DD, Antesia, NM 88210

OIL CONSERVATION DIVISION OIL CONSER. P.O. Box 2088

RECE VED

Santa Fe. New Mexico, 87504-2088

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	1		ABLE AND AUTHOR	92' NZATION	APR 3	AM 9	11	
I.			OIL AND NATURAL O					
Operator Rotary Wire Line		Well API No.						
Rotary Wire Line Service, Inc. Address					30-025-27927			
P.O. Box 2135, Ho	bbs, New Mexi	ico 88241						
Reason(s) for Filing (Check proper box)	~ .		Other (Please exp	olain)				
New Well Recompletion		n Transporter of:	7					
Change in Coamton XX	Oil Casinghead Gas	」Dry Gas └─ Condensate ☐						
If change of operator give name	ETEX SUPPLY	0. Box 72	70 B, Hobbs, NM 882					
and address of previous operator	•	O. DOX PAC	o, nobbs, Nr. 882	40				
II. DESCRIPTION OF WELL Lease Name	AND LEASE Well No.	Dool Name Inch	udina Francisca	12:-4				
Lee Carter	Well No.		Drinkard, West		of Lease Federal ox Fee	L	ease No.	
Location		· · · · · · · · · · · · · · · · · · ·		 L		-1		
Unit LetterH	: 1980	_ Feet From The .	North Line and 66	0 F	eet From The	East	Line	
Section 33 Townsh	_{ip} 16S	Range 37	E , NMPM,	Lea			County	
III. DESIGNATION OF TRAN	SPORTER OF O	IL AND NAT	URAL GAS					
Name of Authorized Transporter of Oil	Address (Give address to w	hich approve	d copy of this forr	n is to be se	ent)			
Texaco Trading & Tra	57 P.O. Box 6196,	Midlan	d, Texas	79711	-0196			
Name of Authorized Transporter of Casin n/a	ghead Gas	or Dry Gas	Address (Give address to w	hich approved	d copy of this form	n is to be se	int)	
If well produces oil or liquids,	Unit Sec.	Twp. Rg	e. Is gas actually connected?	When	1?	· - · · · · · -		
give location of tanks.	Н 33	16S 37E	1 -	i				
If this production is commingled with that	from any other lease or	pool, give commin	ngling order number:					
IV. COMPLETION DATA	louw u	1 0 11 11		,	1 5 5 15			
Designate Type of Completion	- (X) Oil Well	Gas Well	New Well Workover XX	Deepen	Plug Back Sa	me Res'v	Diff Res'v	
Date Spudded 10-21-82	Date Compl. Ready to Prod. 6-5-83		Total Depth	· L	P.B.T.D.	 8579'		
Elevations (DF, RKB, RT, GR, etc.)	Name of Producing Formation		Top Oil/Gas Pay		Tubing Depth			
3778' (DF)	Drinkard		7780					
Perforations 7782'-7937'		Depth Casing Shoe						
TUBING, CASING AND			CEMENTING DECOR	CEMENTING DECORD		7747		
HOLE SIZE	CASING & TU		DEPTH SET		SACKS CEMENT			
172"	13 3/8"		377		550			
11"	8 5/8"		4800			2650		
7 7/8"	55"		11515		2400			
V. TEST DATA AND REQUES				11.6.41		6.U 24 have	1	
	T	of load oil and mu	st be equal to or exceed top allo Producing Method (Flow, pu			Tui 24 now	5.)	
Date First New Oil Run To Tank	Date of Test		Producing Method (Plow, pu	ump, gas tyt, e	ac.)			
Length of Test	Tubing Pressure		Casing Pressure	Casing Pressure		Choke Size		
Actual Prod. During Test	Oil - Bbls.		Water - Bbis.		Gas- MCF			
CAO SUPLI	<u></u>				1			
GAS WELL Actual Prod. Test - MCF/D	Length of Test		Bbls. Condensate/MMCF		Gravity of Cond	lensate		
71000011001100110								
Testing Method (pitot, back pr.)	Tubing Pressure (Shut-in)		Casing Pressure (Shut-in)		Choke Size			
VI. OPERATOR CERTIFIC	ATE OF COMP	LIANCE	011 001		ATION! D!	VICIO	NI	
I hereby certify that the rules and regul-	ations of the Oil Conserv	vation	OIL CON	19FHA	ATION DI		'IN	
Division have been complied with and is true and complete to the best of my!		en above			MAR 3 1	L'92		
and and complete to the test of his !			Date Approve	a		2		
Mokey W	Morn		By Serre	ndle				
Signature Mickey Welborn President								
Printed Name 03-13-92	505-397	Title	Title DIS	STRICT	1 SUPER	/ISOR		
Date		phone No.			= 	. roon		
	. 010	,						

INSTRUCTIONS: This form is to be filed in compliance with Rule 1104

- 1) Request for allowable for newly drilled or deepened well must be accompanied by tabulation of deviation tests taken in accordance with Rule 111.
- 2) All sections of this form must be filled out for allowable on new and recompleted wells.
- 3) Fill out only Sections I, II, III, and VI for changes of operator, well name or number, transporter, or other such changes.