

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| |
|---|
| WELL API NO. 30-025-28132 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. LG 5422 |
| 7. Lease Name or Unit Agreement Name Robin UT State |
| 8. Well No. 1 |
| 9. Pool name or Wildcat Saunders Permo Upper Penn |

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

| | |
|---|--|
| 1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> P&A <input type="checkbox"/> | 2. Name of Operator YATES PETROLEUM CORPORATION |
| 3. Address of Operator 105 South 4th St., Artesia, NM 88210 (505) 748-1471 | 4. Well Location Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line Section 10 Township 15-S Range 33-E NMPM Lea County |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4186.5' GR | |

| | |
|---|--|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | PLUG AND ABANDONMENT <input checked="" type="checkbox"/> |
| | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| | OTHER: <input type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged well and abandoned as follows: RUPU. TOOH with rods, released RBP at 9832' and POH. Set CIBP at 9840' and cap with 35' cement. Set CIBP at 9180' and cap with 25 sacks cement. Circulated hole with mud. POOH with tubing to 7860'. Spot 35 sacks cement. POOH with tubing. RIH with wireline. Shot 4 holes at 5788'. RIH with tubing and cement retainer. Set retainer at 5750'. Squeezed 50 sacks. Ran another wireline. Shot 4 holes at 4175'. Picked up retainer and set retainer at 4100'. Squeezed 50 sacks. Dumped 50' on top of retainer. Pulled up hole to 2650'. Spot 25 sack plug at 2650'. POOH with tubing. Rigged up wireline. Shot 4 holes at 465'. Tie on to casing. Pumped 100 sacks cement down 5-1/2" casing. Circulated back out to 8-5/8". Filled with cement. Installed dry hole marker. Work began 4-15-93 - completed 4-23-93. WELL PLUGGED AND ABANDONED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 12-9-93
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY

Jack Griffin

TITLE

OIL & GAS INSPECTOR

DATE

FEB 21 1994

CONDITIONS OF APPROVAL, IF ANY:

SAC