

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fed ☒
5. State Oil & Gas Lease No.

3D-025-28183

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☐ OTHER- 2. Name of Operator RHOMBUS OPERATING CO, LTD. 3. Address of Operator 200 W. Lorraine, Suite 1270, Midland, TX. 79701 915-683-8873 4. Location of Well UNIT LETTER L 1830 FEET FROM THE S LINE AND 660 FEET FROM TNE W LINE, SECTION 1 TOWNSHIP 15-S RANGE 36 E NMPM. 15. Elevation (Show whether DF, RT, CR, etc.)	7. Unit Agreement Name 8. Farm or Lease Name Scott 9. Well No. 1 10. Field and Pool, or Wildcat NE Cardill WC 12. County LEA
---	--

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 10,500' - 35' cmt on top TAG
2. 25 SVS @ 9100' - 9000'
3. 50'in & 50'out strb - TAG - estimated recovery 4800±
4. 40 SVS @ 2000' - 1900'
5. 40 SVS @ 468' - 368' TAG
6. 10 SVS @ 30' - SURFACE

Install Dry Hole Marker
Cir 9.5# mud

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Agent DATE 1-26-01

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Ti-