Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

I OUT	C·IM
Revise	ed 1⋅1 €

DISTRICT II Santa Fe, New Mexico 87504-2088	30-025-28183
P.O. Drawer DD, Artesia, NM 88210	5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name
I. Type of Well: OR. GAS WELL X WELL OTHER	Scott
2. Name of Operator	8. Well Na
Harvey E. Yates Company  1. Address of Operator	9. Pool name or Wildcat
P. O. Box 1933 Roswell, New Mexico 88201	N.E. Caudill Wolfcamp
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3874.4' GL (26.8' KB)	NMPM LEA County
11. Check Appropriate Box to Indicate Nature of Notice, R NOTICE OF INTENTION TO: SUE	REPORT, OF Other Data  SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING	
CASING TEST AND C	
OTHER: Squeeze	Perfs & Sidetrack
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inclu	iding estimated date of starting any proposed
work) SEE RULE 1103.	
	, Sqz to 3500# c of window @ 10,634') to 10,842 MD (10,836 TVD)
### SEE RULE 1103.  4/29/90 Drill out CIBP @ 10,700'  5/1/90 Run GR/CCL/CBL, from 10,800-10,000', Set Ret  5/2/90 Sqz perfs 10,662 - 10,880' w/300 skx CL "H"  5/4/90 Set Whipstock @ 10,638'. Mill window (bottom 5/7-5/14/90  DRLG w/ bent motor and housing from 10,681' w/ 43' displaced from original hole.	, Sqz to 3500# n of window @ 10,634') to 10,842 MD (10,836 TVD) on.