

NEW MEXICO OIL CONSERVATION COMMISSION

PRODUCTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator H. L. Brown, Jr.	8. Farm or Lease Name State 32
3. Address of Operator P. O. Box 2237, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>S</u> LINE AND <u>660</u> FEET FROM THE <u>E</u> LINE, SECTION <u>32</u> TOWNSHIP <u>15S</u> RANGE <u>32E</u> N.M.P.M.	10. Field and Pool, or Wildcat Wildcat (Canyon)
15. Elevation (Show whether DF, RT, GR, etc.) 4306' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103.

- 10-10-84: Morrow Zone: RU Geosource. Attempt to set through tubing bridge plug two times. Dogs failed to pull out of sleeve. Brought sleeve into shop. SION.
- 10-11-84: Morrow Zone: RU mast. TIH w/cmt. dump bailer. TIH w/through tubing bridge plug. Set at 12,191' (KB) (1' above top of liner).
- 10-12-84: Morrow Zone: WOC to set in through tubing bridge plug (TTBP) so vent tube can be closed. Dumped approximately 3' of cmt.
- 10-13-84: TIH w/impression block to tag top of cmt. Yest.: Tagged top valve at 12,182', tapped on valve and closed. Checked w/second run. Made three runs and dumped 4.8' cmt on top of plug. SION.
- 10-14-84: Morrow Zone: SI. Yest: RIH w/IB & centralizer. Tap top of cmt. at 12,181'. Made 5 runs w/cmt bailer and dumped 8' cmt. Top cmt est. at 12,173'. SION. RD. Final TP 1450 psi.
- 10-15-84: Morrow Zone: SITP 1300#. WO increase in TP and WOC.
- 10-16-84: Morrow Zone: SITP 1300#.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jean Mills TITLE Production Clerk DATE 10-16-84

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE OCT 19 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT 18 1984

RECEIVED
FBI - NEW YORK