

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

5a. Indicate Type of Lease
State ☐ Fee ☒ **XX**
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Reading & Bates Petroleum Company	8. Farm or Lease Name Caswell
3. Address of Operator 2412 N. Grandview, Suite 201, Odessa, Texas 79761	9. Well No. 1
4. Location of Well UNIT LETTER <u>J</u> 1980 FEET FROM THE <u>South</u> LINE AND 1980 FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>T-15-S</u> RANGE <u>R-35-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Townsend Permo Upper Pen
15. Elevation (Show whether DF, RT, GR, etc.) DF 4024.6 GR 3998.6	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: **SUBSEQUENT REPORT OF:**

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/> XX
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

O. C. C. recommendation by Eddy Seay

Load hole 10# salt gel, tag cut off point @ 8200' approx.

- 1st plug: 100' or cast iron plug 35' cement on top above perms 10-220 to 10-320.
- 2nd plug: 100' @ Wolfcamp 9690'
- 3rd plug: 200' @ ABO 8130' across cut off, also across 5½ cross cut off.
- 4th plug: 100' @ Glorieta 6195'
- 5th plug: 100' across intermediate shoe, 4915'
- 6th plug: 200' salt plug @ 1828'
- 7th plug: 100' across surface shoe @ 460'
- 8th plug: 100' across surface plug.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ICED Donald J. Kipgen Donald J. Kipgen TITLE Area Superintendent DATE 10/22/85

APPROVED BY Ronald M. Cantelero TITLE OIL & GAS INSPECTOR DATE MAY 2 - 1986

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT 24 1985

O.C.D.
NOBBS OFFICE