

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SAN CARLO	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATION	

5a. Indicate Type of Lease

State XFor

5. State Oil & Gas Lease No.

30-025-28501

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - I" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER-		7. Unit Agreement Name	
2. Name of Operator Santa Fe Energy Company		8. Farm or Lease Name Feather	
3. Address of Operator 500 W. Illinois, Suite 500, Midland, TX 79701		9. Well No. 1	
4. Location of well UNIT LETTER <u>C</u> <u>1980</u> FEET FROM THE <u>West</u> LINE AND <u>660</u> FEET FROM THE <u>North</u> LINE, SECTION <u>21</u> TOWNSHIP <u>15S</u> RANGE <u>32E</u> NMPM.		10. Field and Pool, or Wildcat Wildcat	
15. Elevation (Show whether DF, RT, GR, etc.) 4307.3' GR		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT
-------------------------	--	-------------------

PERFORM REMEDIAL WORK	☐	PLUG AND ABANDON	☒	REMEDIAL WORK	☐	ALTERING CASING	☐
TEMPORARILY ABANDON	☐			COMMENCE DRILLING OPNS.	☐	PLUG AND ABANDONMENT	☐
PULL OR ALTER CASING	☐	CHANGE PLANS	☐	CASING TEST AND CEMENT JOBS	☐		
OTHER	☐			OTHER	☐		

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PBTD @ 10,315', CIBP @ 9,749'. Load hole w/9.5 ppg mud. Set CIBP @ 9590' w/35' cmt. Shoot off & recover 5½" csg. Spot 100' cmt plug across 5½" csg stub. Tag plug. Spot 100' cmt plug @ 8922-9022' (Wolfcamp top). Spot 100' cmt plug @ 7530-7630' (ABO top). Spot 100' cmt plug @ 5500-5600' (Glorieta top). Spot 100' cmt plug @ 4020-4120' (8-5/8" csg shoe). Tag plug. Set 8-5/8" cmt retainer @ 3900'. Spot 100' cmt plug @ 1400-1500' @ Rustler top. Spot 100' cmt plug from 405-505' across surface csg shoe. Set 10 sx cmt plug @ surface. Cut off wellhead 5' below ground level. Install dry hole marker w/name & location of well.

THE BOARD SHALL NOT BE REQUIRED TO
 CONSIDER ANY OF THE RECOMMENDATIONS OF
 THE BOARD OF DIRECTORS FOR THE C-103

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

P. J. Gaume

P. J. Gaume

TITLE

Sr. Production Engineer

DATE 6/28/85

ORIGINAL SIGNED BY JERRY LEXTON

APPROVED BY

DISTRICT : SUPERVISOR

TITLE

DATE _____

JUL - 2 1985

CONDITIONS OF APPROVAL, IF ANY: