

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
V-192	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Bell Management, Inc.		8. Farm or Lease Name Gulf 16 State
3. Address of Operator P. O. Box 1618, Fallon, Nevada 89406		9. Well No. 1
4. Location of Well UNIT LETTER I 1980 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 16 TOWNSHIP 16S RANGE 33E NMPM.		10. Field and Pool, or Wildcat <i>Underlying West Ham Creek</i>
15. Elevation (Show whether DF, RT, GR, etc.) 4218' GL		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

03/19/84 Spotted 50 sx plug 3650' to 3150'. SION & WOC.  
03/20/84 Tagged plug @ 3120'. Spotted 20 sx 1550' to 1350'.  
Spotted 20 sx 400' to 200'. Spotted 10 sx at surface.  
Erected dry hole marker. Cleaned and leveled location.

Note: Hole loaded w/10# gelled brine between plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>Harry L. Scott</i>	TITLE Agent	DATE 03/26/84
APPROVED BY <i>Jack Griffin</i>	TITLE OIL & GAS INSPECTOR	DATE SEP 1 1984
CONDITIONS OF APPROVAL, IF ANY:		