

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 1539	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A		7. Unit Agreement Name
Name of Operator Yates Petroleum Corporation		8. Farm or Lease Name Phillips YX State
Address of Operator 207 South 4th St., Artesia, NM 88210		9. Well No. 1
Location of Well UNIT LETTER M, 990 FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 15S RANGE 36E NMPM.		10. Field and Pool, or wildcat Dean Permo-Penn
11. Elevation (Show whether DF, RT, GR, etc.) 3842.5' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal permission obtained from Eddie Seay, NMOCD, Hobbs, 10-7-85, to plug and abandon well as per C-103 dated 10-3-85.

10-9-85. Spotted 35' cement on RBP at 11455'.
Set CIBP at 10968' w/35' cement on top.
Set CIBP at 10645' w/35' cement on top.
Shot 120 jts 5-1/2" 17# casing off at 6500'.
10-14-85. Spotted 35 sx cement plug at 6554'. WOC 2 hrs. Tagged plug at 6410'.
Spotted 35 sx cement plug at 4953'. WOC 2 hrs. Tagged plug at 4820'.
Spotted 35 sx cement plug at 2213'.
Spotted 50' cement plug to surface.
Set regulation abandonment marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jack Griffin TITLE Production Supervisor DATE 10-17-85
APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE FEB 24 1987
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT 18 1985

O.C.D.
HOBBS OFFICE