

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
LG 1539

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Phillips YX State
3. Address of Operator 207 South 4th St., Artesia, NM 88210	9. Well No. 1
4. Location of Well UNIT LETTER M 990 FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 15S RANGE 36E NMPM.	10. Field and Pool, or Wildcat Dean Permo-Penn
15. Elevation (Show whether DF, RT, GR, etc.) 3842.5' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER Perforate, Treat <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 11727'. WIH and perforated 11525-30' w/10 .50" holes (2 SPF). RIH w/tubing and packer. Acidized 11525-30' w/2500 gallons 20% NEFE acid, 1% KCL and 8 ball sealers. Swabbed well. POOH w/packer. WIH and perforated 10695-10700' w/10 .40" holes (2 SPF). RIH w/packer and RBP. Set RBP and tested. Acidized perms 10695-10700' w/2500 gallons 15% NE acid, 1% KCL and 8 ball sealers. POOH w/packer. RBP set 11448'. Prep to set pumping equipment.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Jerry Sexton</u>	TITLE <u>Production Supervisor</u>	DATE <u>4-18-84</u>
ORIGINAL SIGNED BY JERRY SEXTON		
DISTRICT 1 SUPERVISOR		
APPROVED BY _____	TITLE _____	DATE _____
OF APPROV. ANY:		

APR 23 1984

RECEIVED

APR 20 1984

O. G. D.  
HOBBS OFFICE