STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

DISTRIBUTION			
SANTA FE			
FILE			
U.S.G.S.			
LAND OFFICE			
OPERATOR	T		

OIL CONSERVATION DIVISION

}	DISTRIBUTION							Farm C 183	
<u> </u>				P. O. BO				Form C-103 Revised 10-1-	
	HTA FE			SANTA FE, NEW	/ MEXICO 87501			WELLIG 13-14	
710							Sa. Indicate Type	of Lease	
) ——	1.0.8.		 				State X	Fee 🗍	
	NO OFFICE						5, State Oil & Ga		
OF	ERATOR		L				1	s Lease No.	
				···-	· · · · · · · · · · · · · · · · · · ·		NM 2818		
		SUN	DRY NOTICES	AND REPORTS ON	WELLS				
•	EIHT 3EU TON OO! U	FORM FOR	PROPOSALS TO DRIL	AND REPORTS ON	SACE TO A DIFFERENT RES	ERVOIR,			
1.							7. Unit Agreemen	it Name	
OIL		**.					1		
WELL		פננ נ	OTHER-						
2. Name of Operator							8. Farm or Lease	- Mame	
Amerada Hess Corporation							State 9		
3. Address	s of Operator						9. Well No.		
Drav	wer D. Mon	ument.	New Mexico	88265			1		
4. Locatio				· · · · · · · · · · · · · · · · · · ·	 	··	10. Field and Po	ol, or WildcaStra	
1 -			660	Month	1000	•	-		
UNIT	LETTERD		766	FROM THE North	LINE AND	FEET FROM	NE Loving	con renn -	
1									
THE _	East	LINE S	ECTION 9	TOWNSHIP 16S	37E		$\prime\prime\prime\prime\prime\prime\prime\prime\prime\prime\prime\prime$	///////////////////////////////////////	
'"-						MPM.	MIIIIII	///////////////////////////////////////	
mr^{\prime}	THITTHE	TTTT	11111111	Elevation (Show whether	DF. RT. GR. etc.)		12, County	<i>HHHHH</i>	
		/////							
777777		77777.	7777777	3824'	GR	·	Lea	_077777777	
16.		Chec	ck Appropriate	Box To Indicate N	lature of Notice.	Report of Oth	er Data		
	NO		F INTENTION T			-			
	NO	i i CE Oi	FINIENTION	O .	•	SUBSEQUENT	REPORT OF:		
		$\overline{}$		_					
PERFORM	REMEDIAL WORK	\sqcup		PLUG AND ABANDON	REMEDIAL WORK	X	ALTER	ING CASING	
TEMPORAR	TILY ABAHDON				COMMENCE DRILLING O	PHS.	PLUG A	ND ABANDONMENT	
PULL OR A	LTER CASING			CHANGE PLANS	CASING TEST AND CEMI	ENT JOS			
								۲	
				. —	OTHER			L	
OTHER					,				
12 December	th - Decreed of	Complete	d Operations /Clear	ly state all pertinent det	aile and sine persinent	datas insludina	actimated data of		
	SEE RULE 110		a Operations (Crear	.y state an periment det	ans, and give periment	autes, including	estimated date of .	starting unty propose	
•									
July	y 20, 1988	•							
0)	, _,,								
11	1 11				/211	£ 11 E4	/	0 1	
				Strawn Zone 5-1.					
w/15	500 gal. l	5% NEF	E HCL dbl.	nh. acid mixed	w/15 gal. of X	Kylene. Sw	abbed load	Š	
resi	umed flowi	ng wel	1.						
		_							
								·	
			•						
	•								
		. 1-10	llon shows in the			1.4			
18. I hereb	y certify that the	: intormat	non apove is true a	nd complete to the best of	it my knowledge and bel	iel.			
	() //1.	1/ /							
	K H III	ules	. (/,	TITLE	Supv. Adm. Svc.		DATE 8-	4-88	
SIGNED		4			CEP V. Mains DVC.	, 			
	A84 0111								
	URIGINAL	SIGNED	BY JERRY SEXT	ON	·		AHO	fi a são	
APPROVED 8	vDis	TRICT	SUPERVISOR	TITLE			DATE AUG	<u>∨ 1 00</u>	
		•							