

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.E.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

L CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1.

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

|                                                                                                                                              |                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>                             | 7. Unit Agreement Name                                                 |
| 2. Name of Operator<br>Sun Exploration & Production Company                                                                                  | 8. Farm or Lease Name<br>State Land 76                                 |
| 3. Address of Operator<br>P.O. Box 1861 Midland, TX 79702                                                                                    | 9. Well No.<br>3                                                       |
| 4. Location of Well<br>UNIT LETTER I 660 FEET FROM THE East LINE AND 4720 FEET FROM THE South LINE, SECTION 2 TOWNSHIP 16-S RANGE 32-E NMPM. | 10. Field and Pool, or Wildcat<br>North Anderson Ranch<br>Cisco Canyon |
| 11. Elevation (Show whether DF, RT, GR, etc.)                                                                                                | 12. County<br>Lea                                                      |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

OTHER Acdz.

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPS. ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐  
ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MI RU PU. ND WH. POH w/rods and pump. NU BOP. Rise TAC and tag PBTD. Drop S.V. & test tbg to 5000 PSI. Tally tbg out of hole.
2. RIH w/5½" RTTS pkr and SN on 2-7/8" tbg to ±10400. Set pkr and load backside w/2% KCL fresh wtr.
3. RU Howco. Trap 1500 psi CP. Howco acidize Canyon perms 10511-10517 w/8000 gals gelled brine and 6000 gals gelled 20% NEFE HCL in 2 stages at 8 BPM. Anticipated treating pressure 5000 psi. Max treating pressure 6500 psi. Pump schedule as follows:
  - A. Pump 4000 gal gelled 10#/gal clear brine.
  - B. Pump 3000 gal gelled 20% NEFE HCL + 1000 SCF N<sub>2</sub>/bbl.
  - C. Repeat steps "A" thru "B" once.
  - D. Pump 5000 gals gelled 2% KCL flush + 1000 SCF N<sub>2</sub>/bbl.
4. Flow/swab back L&AW. Recover load ASAP. Rise pkr and POH.
5. POP as before and test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Associate Accountant

DATE 12-27-85

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE

JAN 2 - 1986

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

DEC 31 1985

HOME OFFICE