

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry Hole</u>		7. Unit Agreement Name
2. Name of Operator <u>TXO Production Corp.</u>		8. Farm or Lease Name <u>Carter "F"</u>
3. Address of Operator <u>900 Wilco Bldg., Midland, TX 79701</u>		9. Well No. <u>1</u>
4. Location of Well UNIT LETTER <u>I</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>33</u> TOWNSHIP <u>16-S</u> RANGE <u>37-E</u> N.M.P.M.		10. Field and Pool, or Wildcat <u>Undes. Casey Strawn</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3771.5 GR</u>		12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-12-85 thru 3-6-85 Drlg.
P & A well @ 2100'.
Circ Howco Spot 45 sx "H" @ 11,450'.
45 sx "H" @ 11,100'.
45 sx "H" @ 10,050'.
45 sx "H" @ 8300'.
45 sx "H" @ 6200'.
45 sx "H" @ 4811'.
35 sx "H" @ 2100'.
35 sx "H" @ 500'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Production Clerk</u>	DATE <u>4-9-85</u>
APPROVED BY <u>Jack Griffin</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>JUL 25 1985</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

APR 15 1985

C.C.D.
FIELD OFFICE

RECEIVED BY
APR 14 1985
O. C. D.
ARTESIA, OFFICE