

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name No. Anderson Ranch
2. Name of Operator H. L. Brown, Jr.	8. Farm or Lease Name No. Anderson Ranch
3. Address of Operator P. O. Box 2237 Midland, Texas 79702	9. Well No. 5
4. Location of Well UNIT LETTER <u>I</u> 1980 FEET FROM THE <u>South</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>15S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or Wildcat No. Anderson Ranch Cisco/Canyon
15. Elevation (Show whether DF, RT, GR, etc.) 4314' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 4-1-86 RU Pulling Unit & Apollo WL Truck. Ran 5-1/2" CIBP to 9302', plug hung up. Recieved permission from Jerry Sexton w/NMOCC to set plug @ 9302'. Set plug & pumped 35' cmt on top of plug. PU & TIH w/235 jts 2-3/8" tbg to 7892'. RU Howco Loaded hole w/165 bbl gelled brine. Spotted 10 sxs cmt from 7892' to 7792' (100').
- 4-2-86 TOH w/tbg. perf'd @ 4220'. TIH w/Baker retainer, set @ 4180'. sqz w/50 sxs & left 20sxs cmt in pipe, dumped 1 sx cmt on top of retainer. TOH. Perf @ 1265'. TIH w/tbg & Baker 5-1/2" cmt retainer, set @ 1245'. sqz 15 sxs & left 20 sxs cmt in pipe, dumped 1 sxs cmt on top of retainer. TOH. Set 10' plug @ surface. Cut off wellhead, RD Pulling unit. Welded cap on csg & installed marker. Cut off anchors, cleaned workover pit & cleaned cellar.

Location to be cleared by May 1, 1986.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jean Mills Jean Mills

TITLE Production Clerk

DATE 4-10-86

APPROVED BY Jack Griffin
CONDITIONS OF APPROVAL, IF ANY:

TITLE OIL & GAS INSPECTOR

DATE MAY 6 - 1986

RECEIVED
APR 11 1986
O.C.D.
HOBBS OFFICE