

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☒ Fee ☐

5. State Oil & Gas Lease No.  
E-1075

7. Unit Agreement Name

8. Farm or Lease Name  
ARCO STATE

9. Well No.  
1

10. Field and Pool, or Wildcat  
Dean Devonian

12. County  
Lea

15. Elevation (Show whether DF, RT, GR, etc.)  
GR 3861.6

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
Bliss Petroleum, Inc.

3. Address of Operator  
P. O. Box 1817 Hobbs, N. M. 88240

4. Location of Well  
UNIT LETTER E 2310 FEET FROM THE North LINE AND 830 FEET FROM West LINE, SECTION 35 TOWNSHIP 15S RANGE 36E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
GR 3861.6

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐ OTHER ☐ CASING TEST AND CEMENT JOBS ☒

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded @ 7:00 AM on 4-25-85.  
MI Rotary Rig. Drlg. 17 1/2" hole to 352'. Set new 13 3/8", 54.5# csg. @ 349.72 - and cement with 400 sacks class "C" & 2% CaCl<sub>2</sub> & 1/4# sack cello-seal. Circulate cement to surface. Bump plug to 450#. Plug dwn. @ 12:46 PM on 4-27-85. Release Press. Cut off 13 3/8" & weld on csg. hd. Test csg. to 700# for 1 hr. before drlg. out. Held ok.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Paul Bliss TITLE PRESIDENT DATE 4-30-85

APPROVED BY                      TITLE                      DATE                     

CONDITIONS OF APPROVAL, IF ANY: