

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

| |
|---|
| WELL API NO. 30-025-29248 |
| 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No. |
| 7. Lease Name or Unit Agreement Name Carter |
| 8. Well No. 2 |
| 9. Pool name or Wildcat Lovington Penn, NE |

| | |
|---|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER | |
| 2. Name of Operator Amerind Oil Company Limited Partnership | |
| 3. Address of Operator 415 W. Wall, Suite 500, Midland TX 79701-4467 | |
| 4. Well Location Unit Letter <u>G</u> : <u>1330</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>28</u> Township <u>16S</u> Range <u>37E</u> NMPM Lea County | |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3788' GL | |

| | |
|---|---|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | OTHER: <input type="checkbox"/> |
| PLUG AND ABANDON <input checked="" type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| CHANGE PLANS <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Set CIBP @ 11,300' w/35' cement cap.
- Displace with 10 lb/gal brine water & 25 lb gel/bbl.
- Plug No. 2 30 sx @ 8900'
Plug No. 3 30 sx @ 6350'
- Cut 5-1/2" csg @ 4480' and recover.
- Plug No. 4 60 sx @ 4850' (tag)
Plug No. 5 45 sx @ 2200'
Plug No. 6 10 sx @ surface
- Weld on dry hole marker. Salvage equipment. Clean and level location.
- Report.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE CIBP TO BE APPROVED

set 100' plug @ 3245 over base fault
set 40' plug 40 in / 50' interval shoe
340' - 440'

(Anticipated plugging date ASAP)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James E. Yeley TITLE Agent DATE 08/16/1999
TYPE OR PRINT NAME James E. Yeley TELEPHONE NO. 915/682-8217

(This space for State Use)

Orig. Signed by
Paul Gaultz
Geologist

APPROVED BY _____ TITLE _____ DATE AUG 20 1999
CONDITIONS OF APPROVAL, IF ANY: