

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-29256 ✓
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	LG-2943
7. Lease Name or Unit Agreement Name Lovely State	
8. Well No.	1
9. Pool name or Wildcat	N. Anderson Ranch (Wolfcamp)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4287 GR	

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator H. L. Brown, Jr.
3. Address of Operator P. O. Box 2237, Midland, Texas 79702	4. Well Location Unit Letter <u>E</u> : <u>2173</u> Feet From The <u>North</u> Line and <u>467</u> Feet From The <u>West</u> Line

Section 15 Township 15 S Range 32 E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU Pride Well Service. Pulled rods and tubing. Set 5 1/2" CIBP @ 9700' w/ 5 sx Class "C" cement on top. Set 25 sx Class "C" cement plugs at: 7000-6900', 6050-5950', 5030-4930', 4150-4050'.

Cut and laid down 543' 5 1/2" casing.

Set 35 sx Class "C" cement plug at 603-433', and set 15 sx Class "C" cement (25') plug at surface. Welded on 1/2" plate. Set wellbore marker and filled in cellar and working pit.

Well P & A 3/25/93

Prep to clean and recondition location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Matthew A. Doffer TITLE Production Engineer DATE 3/26/93

TYPE OR PRINT NAME Matthew A. Doffer TELEPHONE NO. 915-683-5216

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE SEP 22 1993

CONDITIONS OF APPROVAL, IF ANY:

**RECEIVED**

**APR 05 1993**

**OCD HOBBS OFFICE**