

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Amerada Hess Corporation	8. Farm or Lease Name Andrus 9
3. Address of Operator Drawer D, Monument, New Mexico 88265	9. Well No. 1
4. Location of Well UNIT LETTER <u>L</u> <u>1874</u> FEET FROM THE <u>South</u> LINE AND <u>766</u> FEET FROM THE <u>West</u> LINE, SECTION <u>9</u> TOWNSHIP <u>16S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or WHdcat N.E. Lovington Penn
15. Elevation (Show whether DF, RT, GR, etc.) 3842' KB, 3841' DF, 3823' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-19 to 7-22-87

MIRU pulling unit & pulled rods, pump & tbg. McCullough perf. Strawn Zone 5-1/2" csg. fr. 11556' to 11559' w/2SPF using 3-1/8" Alpha jet csg. gun. Total of 7 holes at .42" diameter/hole w/17" penetration. Ran pkr. & set at 11545'. Western Co. attempted to acidize Strawn Zone new 5-1/2" csg. perfs. fr. 11556' to 11559' w/500 gal. 15% NEFE dbl. inh. acid. New perfs. communicated w/perfs. above pkr. fr. 11551' to 11501'. Recovered pkr. & re-ran tbg., pump & rods & resumed pumping.

Test of 8-2-87: Pumped 33 b.o. & 135 b.w. in 24 hours w/7 x 144" SPM.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. L. Whaley, Jr. TITLE Supv. Adm. Svc. DATE 8-4-87

ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT 1 SUPERVISOR TITLE _____ DATE AUG 10 1987
CONDITIONS OF APPROVAL, IF ANY: