

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 30-025-29535
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: College of the Southwest 17
8. Well No. 1
9. Pool name or Wildcat Lovington Penn West

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other T.A.'d
Name of Operator Chesapeake Operating, Inc.

2. Address of Operator
P.O. Box 18496, Oklahoma City, OK 73154-0496

3. Well Location
Unit Letter M : 981 feet from the South line and 991 feet from the West line
Section 17 Township 16-S Range 36-E NMPM Lea County
10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3,544' GL; 3,555' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

05/07/02 Notified OCD, Gary Wink. MIRU Triple N rig #25 and NU BOP. POOH w/ tbg and packer, SDFN.

05/08/02 Finished POOH w/ tubing and packer. Set CIBP @ 10,648'. Circulated hole w/ mud and pumped 25 sx C cmt 10,648 - 10,399'. Pumped 25 sx C cmt 8,144 - 7,890'. POOH w/ tbg and SDFN.

05/09/02 Tagged cmt @ 7,880'. Pumped 25 sx C cmt 6,275 - 6,021'. Pumped 25 sx C cmt 4,373 - 4,119'. WOC and tagged cmt @ 4,113'. Pumped 25 sx C cmt 1,806 - 1,552'. Circulated 50 sx 475' to surface. RDM 29.7031

05/21/02 Cut off wellhead and installed dry hole marker, cut off anchors, backfilled collar and pit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James F. Newman TITLE Engineer DATE 05/21/02
Type or print name James F. Newman, P.E. Triple N Services, Inc. Telephone No. 915-687-1994
(This space for State use)

APPROVED BY Billy E. Newman TITLE COMPLIANCE OFFICER DATE JUL 4 2002
Conditions of approval, if any: GW