

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-29581
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Amerind Oil Company Limited Partnership		6. State Oil & Gas Lease No.
3. Address of Operator 415 West Wall Street, Suite 500, Midland TX 79701		7. Lease Name or Unit Agreement Name: Meyers
4. Well Location Unit Letter <u>C</u> : <u>660</u> feet from the <u>North</u> line and <u>2130</u> feet from the <u>West</u> line Section <u>33</u> Township <u>16S</u> Range <u>37E</u> NMPM Lea County		8. Well No. 1
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3787' GL, 3801' KB		9. Pool name or Wildcat Casey Strawn, West

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Set CIBP @ 11,550' w/35' cement cap.
2. Displace with 10 lb/gal brine water w/25 lb gel/bbl.
3. Set 30 sx @ 8,150'. — TAG
4. Set 30 sx @ 5,150'.
5. Cut 5-1/2" csg @ 4,100' and recover.
6. Set 70 sx @ 4,260' and tag.
7. Set 45 sx @ 2,170'.
8. Set 45 sx @ 455' and tag.
9. Set 10 sx @ surface.
10. Weld on dry hole marker. Salvage equipment. Clean and level location. Report.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

CONDITIONS OF APPROVAL

All pits must be lined with plastic

All shoe plugs, stub plugs & cement plugs above perforations must be tagged

I hereby certify that all cement plugs pumped minimum 25 sxs & be minimum 100 feet

of my knowledge and belief.

SIGNATURE [Signature] TITLE Agent DATE 03/20/2002

Type or print name James E. Yeley

Telephone No. 915/682-8217

(This space for State use)

APPROVED BY

Conditions of approval, if any:

DATE SIGNED BY
GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE MAR 26 2002