

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-29712

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

HUDGENS

8. Well No.  
1

9. Pool name or Wildcat N. Lovington  
WILDCAT WOLF CAMP ataka gas

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator  
NORTH AMERICAN ROYALTIES, INC.

3. Address of Operator  
306 W. WALL-SUITE 1400, MIDLAND, TEXAS 79701

4. Well Location  
Unit Letter J : 1980 Feet From The SOUTH Line and 1980 Feet From The EAST Line  
Section 11 Township 16-S Range 36-E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3883' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-14-91 RIH with wireline CIBP and set at 10,196'. RIH with bailer and put 35' of cement on top of CIBP. RIH with tubing and spotted 100' cement plug at 7000' with mud laden fluid. Shot casing off at 5500'.

3-15-91 Pulled 5500' of 5-1/2" casing. RIH with tubing to 5511' and spotted 100' cement plug with mud laden fluid. POOH to 3-5/8" casing shoe and spotted 100' cement plug with mud laden fluid. POOH to 1300' and spotted 100' cement plug with mud laden fluid. Put 10 sx cement plug at surface. Welded on plate and dry hole marker. WELL PLUGGED AND ABANDONED 3-15-91.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kevin L. Widner TITLE PETROLEUM ENGINEER DATE 3-22-91

TYPE OR PRINT NAME KEVIN L. WIDNER TELEPHONE NO. 915/683-4836

(This space for State Use)

APPROVED BY Lyle F. Turnacliffe TITLE OIL & GAS INSPECTOR DATE JUL 08 1991  
CONDITIONS OF APPROVAL, IF ANY: