

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-02529764
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	LG-4717
7. Lease Name or Unit Agreement Name	Chevron State
8. Well No.	#1
9. Pool name or Wildcat	Undesignated Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Hondo Drilling Company

3. Address of Operator
P.O. Drawer 2516, Midland, TX 79702-2516

4. Well Location
Unit Letter E : 1,980 Feet From The North Line and 660' Feet From The West Line
Section 8 Township 16-S Range 33-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Wolfcamp zone - Perforated from 10,646' to 10,654'; total 8', 2 shots per foot.
Set cast iron Bridge Plug at 10,570', dumped 40' cement on top Bridge Plug.
Estimated top cement 5 1/2" casing at 8,720'. Free-point 5 1/2" casing and pull same from 8,650'. 25 sacks cement plug set at 8,600', 25 sack cement plug set 5,825' top Glorieta, 25 sacks cement plug set at 4,450' bottom of 8 5/8" casing, cement circulated on 8 5/8" casing, 25 sacks cement plug set at 1,525', 25 sacks cement plug top of 8 5/8" casing with Abandonment Marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE President DATE June 3, 1991

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY Paul J. [Signature] TITLE Geologist DATE JUN 15 1991

CONDITIONS OF APPROVAL, IF ANY: